



## Glass Doors

Subfolders (total): 0



**# 615 31 7/8 x 77 3/4 x 1 3/8**




**# 616 29 3/4 x 76 3/4 x 1 3/8**



**#115. 31 3/4 x 79 1/4 x 1 3/8**

Tags: Chippy/Cracked Paint, Wavy Glass, Architectural Details

Notes: Wavy Glass. Starburst design. Belmond, Iowa.



### #140 33 3/4 x 81 1/2 x 1 3/4

Tags: Exterior

Notes: No glass, exterior door. Des Moines, IA



### #159. 33 7/8 x 83 3/4 x 1 3/4


Tags: Chippy/Cracked Paint, Exterior

Notes: Found in an abandoned warehouse in Des Moines, IA. Beautiful aging.



### #180 33 1/2 x 83 x 1 3/8

Notes: Emmetsburg, IA. Missing piece of trim on bottom



### #197 36 1/4 x 83 1/2 x 1 3/4

Notes: 2" needs cut off



### #213 34 x 89 5/8 x 1 3/4

Tags: 89 inches and taller

Notes: Pemberton, IA. BEVELED GLASS



### #249 35 3/4 x 78 1/2 x 1 3/8

Notes: Emmetsburg, IA



### #287 35 3/4 x 82 1/2 x 1 3/4

Tags: Exterior, Ready to Hang, Beveled Glass


Notes: Beautiful door in EXCELLENT condition!! Hampton, IA



### #315. 36 x 82 x 1 3/8

Tags: Chippy/Cracked Paint

Notes: Antique Door in Oelwein, IA



### #330 30 3/4 x 84 x 2 3/8

Tags: Ready to Hang

Notes: Part of a French door. Can remove the lip.



### #342 31 7/8 x 79 1/2 x 1 1/2

Tags: Chippy/Cracked Paint, Needs Work

Notes: Crack in glass. Oelwein, IA



### #35 32 x 84 x 1 3/4

Notes: Algona, Iowa



### #386 32 x 79 1/4 x 1 3/8



**#426 32x79 1/4x1 3/8**



**#428 32x78 3/4x1 3/8**



**#447 35 3/4x79 1/4x1 3/8**



**#483 35 3/4 x 82 7/8 x 1 3/4**

**Tags:** Exterior, cracked glass

**Notes:** Beautiful door. Notice patches below. Dayton, Iowa



**#502 36 x 79 3/4 x 1 3/4**

Tags: Unique, Exterior

Notes: Thayer Iowa Great front entry



**#522 34 x 79 3/4 x 1 3/8**

Tags: Architectural Details



**#524 34x 82 1/4x 1 1/4**

Tags: MCM



**#527 36x84 1/4x1 3/4**

Tags: Snowflake Glass



**#531 33 3/4x 82x 1 3/4**


Tags: MCM



**#532 32 x 80 x 1 3/8**

Tags: Architectural Details

Notes: In VGHM



**#546 35 1/2x 93 1/2x 1 3/4**

Tags: 89 inches and taller



**#547 35 1/2x 93 1/2x 1 3/4**

Tags: 89 inches and taller



**#601 38 1/8 x 84 5/8 x 1 3/4**



**#602 79 3/8 x 32 x 1 1/4**



**#605 35 7/8 x 78 3/4 x 1 3/4**



**#607 34 x 81.5 x 1.75**





**#610 36 1/4 x 80 3/4 x 1 3/4**



**#612 33 5/8 x 83 3/4 x 1 3/4**



**#620 35 3/4 x 77 3/8 x 1 5/8**



**#622 34 x 82 x 1 3/4**



**#623 36 x 79 3/4 x 1 3/4**



**#625 36 x 78 1/2 x 1 3/4**



**#626 31 5/8 x 79 3/8 x 1 3/4**



**#635 31 7/8 x 78 5/8 x 1 3/8**

Tags: Architectural Details, Beveled Glass



**#636 36 x 81 1/2 x 1 3/4**

Notes: Oelwein, IA



**#637 35 3/4 x 88 5/8 x 1 3/4**

Tags: Exterior, 89 inches and taller

Notes: Decorah Iowa



**#638 36 x 89 1/2 x 2 1/8**

Tags: Wavy Glass, Exterior, Ready to Hang, 89 inches and taller

Notes: Kansas City, KS



**#639 31 5/8 x 89 3/8 x 1 3/8**



**#640 35 7/8 x 83 5/8 x 1 3/4**

Tags: Exterior, Ready to Hang

Notes: Bloomington, Illinois



**#76. 30 x 76 1/2 x 1 3/8**

Tags: Chippy/Cracked Paint

Notes: Old Farmhouse from Iowa



**#90. 35 7/8 x 90 x 1 1/4**

Tags: Unique, Ready to Hang, 89 inches and taller

Notes: Unique tall door with mail slot. Northwood, Iowa. Uneven cut at the bottom



**31 7/8 x 79 3/8**